


NIKKEN TURNING SKILL REAMER FOR CNC AUTOMATIC TURNING MACHINE




SRST-F

For THROUGH HOLE, STEPPED HOLE
Turning skill Reamer (Short Shank)



Explanation of the Code No.

SRST - **10.0** - **F**
 • FOR STEPPED HOLE
 • DIAMETER
 • TURNING SKILL REAMER SERIES
 SRST : STRAIGHT SHANK SHORT



MILLING BLADE

LH-HELIX 45°

PN

P.140

*See P.4 for icons.

STOCK: ●=STANDARD STOCK ITEM(IN JAPAN) △=PRODUCTION BY ORDER

Code No.	STOCK	DC H7	OAL	DCON	PL	DCN	LCF	LH
SRST-2.98F	△	2.98						
-2.99F	△	2.99	60	3	0.6	1.5	20	35
-3.0 F	●	3.0						
-3.01F	△	3.01						
-3.02F	△	3.02						
-3.03F	△	3.03						
-3.04F	△	3.04	60	3	0.6	1.5	20	35
-3.05F	△	3.05						
-3.1 F	△	3.1						
-3.2 F	△	3.2						
-3.3 F	△	3.3						
-3.4 F	△	3.4						
-3.5 F	△	3.5						
-3.6 F	△	3.6						
-3.7 F	△	3.7						
-3.8 F	△	3.8						
-3.9 F	△	3.9	60	3	0.6	1.5	20	20
-3.95F	△	3.95						
-3.96F	△	3.96						
-3.97F	△	3.97						
-3.98F	△	3.98						
-3.99F	△	3.99						
-4.0 F	●	4.0						
-4.01F	△	4.01						
-4.02F	△	4.02						
-4.03F	△	4.03						
-4.04F	△	4.04	60	3	0.6	1.5	20	20
-4.05F	△	4.05						
-4.1 F	△	4.1						
-4.2 F	△	4.2						
-4.3 F	△	4.3						
-4.4 F	△	4.4						
-4.5 F	△	4.5						
-4.6 F	△	4.6						
-4.7 F	△	4.7						
-4.8 F	△	4.8						
-4.9 F	△	4.9	65	4	0.6	2	25	25
-4.95F	△	4.95						
-4.96F	△	4.96						
-4.97F	△	4.97						
-4.98F	△	4.98						
-4.99F	△	4.99						
-5.0 F	●	5.0						
-5.01F	△	5.01						
-5.02F	△	5.02						
-5.03F	△	5.03						
-5.04F	△	5.04	65	4	0.6	2	25	25
-5.05F	△	5.05						
-5.1 F	△	5.1						
-5.2 F	△	5.2						
-5.3 F	△	5.3						
-5.4 F	△	5.4						
-5.5 F	△	5.5						
-5.6 F	△	5.6	65	5	0.6	3	25	25
-5.7 F	△	5.7						
-5.8 F	△	5.8						
-5.9 F	△	5.9						
-5.95F	△	5.95						

Code No.	STOCK	DC H7	OAL	DCON	PL	DCN	LCF	LH
SRST-5.96F	△	5.96						
-5.97F	△	5.97	65	5	0.6	3	25	25
-5.98F	△	5.98						
-5.99F	△	5.99						
-6.0 F	●	6.0						
-6.01F	△	6.01						
-6.02F	△	6.02						
-6.03F	△	6.03						
-6.04F	△	6.04	65	5	0.6	3	25	25
-6.05F	△	6.05						
-6.1 F	△	6.1						
-6.2 F	△	6.2						
-6.3 F	△	6.3						
-6.35F	△	6.35						
-6.4 F	△	6.4						
-6.5 F	△	6.5						
-6.6 F	△	6.6						
-6.7 F	△	6.7						
-6.8 F	△	6.8	70	6	0.6	3	25	25
-6.9 F	△	6.9						
-6.95F	△	6.95						
-6.96F	△	6.96						
-6.97F	△	6.97						
-6.98F	△	6.98						
-6.99F	△	6.99						
-7.0 F	●	7.0						
-7.01F	△	7.01						
-7.02F	△	7.02						
-7.03F	△	7.03						
-7.04F	△	7.04	70	6	0.6	3	25	25
-7.05F	△	7.05						
-7.1 F	△	7.1						
-7.2 F	△	7.2						
-7.3 F	△	7.3						
-7.4 F	△	7.4						
-7.5 F	△	7.5						
-7.6 F	△	7.6						
-7.7 F	△	7.7						
-7.8 F	△	7.8						
-7.9 F	△	7.9	70	6	0.6	3.5	25	25
-7.95F	△	7.95						
-7.96F	△	7.96						
-7.97F	△	7.97						
-7.98F	△	7.98						
-7.99F	△	7.99						
-8.0 F	●	8.0						
-8.01F	△	8.01						
-8.02F	△	8.02						
-8.03F	△	8.03						
-8.04F	△	8.04	70	6	0.6	3.5	25	25
-8.05F	△	8.05						
-8.1 F	△	8.1						
-8.2 F	△	8.2						
-8.3 F	△	8.3						
-8.4 F	△	8.4						
-8.5 F	△	8.5	70	8	0.6	4	25	25
-8.6 F	△	8.6						
-8.7 F	△	8.7						

★PL means chamfering length to Φ DC.

★Turning skill reamer is recommended to use on NC Lathe. P.142

Next page

HSS

FOR THROUGH HOLE

FOR STEPPED HOLE




NIKKEN TURNING SKILL REAMER FOR CNC AUTOMATIC TURNING MACHINE




SRST-F

For THROUGH HOLE, STEPPED HOLE
Turning skill Reamer (Short Shank)



Explanation of the Code No.

SRST - **10.0** - **F**
 • FOR STEPPED HOLE
 • DIAMETER
 • TURNING SKILL REAMER SERIES
 SRST : STRAIGHT SHANK SHORT



MILLING BLADE

LH-HELIX 45°

PN

P.140

*See P.4 for icons.

STOCK: ●=STANDARD STOCK ITEM(IN JAPAN) △=PRODUCTION BY ORDER

Code No.	STOCK	DC H7	OAL	DCON	PL	DCN	LCF	LH
SRST-8.8 F	△	8.8	70	8	0.6	4	25	25
-8.9 F	△	8.9						
-8.95 F	△	8.95						
-8.96 F	△	8.96						
-8.97 F	△	8.97						
-8.98 F	△	8.98						
-8.99 F	△	8.99						
-9.0 F	●	9.0						
-9.01 F	△	9.01						
-9.02 F	△	9.02						
-9.03 F	△	9.03	70	8	0.6	4	25	25
-9.04 F	△	9.04						
-9.05 F	△	9.05						
-9.1 F	△	9.1						
-9.2 F	△	9.2						
-9.3 F	△	9.3						
-9.4 F	△	9.4						
-9.5 F	△	9.5						
-9.52 F	△	9.52						
-9.6 F	△	9.6						
-9.7 F	△	9.7	70	8	0.6	4.5	25	25
-9.8 F	△	9.8						
-9.9 F	△	9.9						
-9.98 F	△	9.98						
-9.99 F	△	9.99						
-10.0 F	●	10.0						
-10.01F	△	10.01						
-10.02F	△	10.02						
-10.03F	△	10.03						
-10.04F	△	10.04						
-10.05F	△	10.05						
-10.1 F	△	10.1						

Code No.	STOCK	DC H7	OAL	DCON	PL	DCN	LCF	LH						
SRST-10.2 F	△	10.2	70	8	0.6	4.5	25	25						
-10.3 F	△	10.3												
-10.4 F	△	10.4												
-10.5 F	△	10.5												
-10.6 F	△	10.6							80	10	0.6	4.5	30	30
-10.7 F	△	10.7												
-10.8 F	△	10.8												
-10.9 F	△	10.9												
-11.0 F	●	11.0												
-11.01F	△	11.01												
-11.02F	△	11.02												
-11.03F	△	11.03												
-11.04F	△	11.04												
-11.05F	△	11.05												
-11.1 F	△	11.1	80	10	0.6	5.5	30	30						
-11.2 F	△	11.2												
-11.3 F	△	11.3												
-11.4 F	△	11.4												
-11.5 F	△	11.5												
-11.6 F	△	11.6												
-11.7 F	△	11.7												
-11.8 F	△	11.8												
-11.9 F	△	11.9												
-11.98F	△	11.98												
-11.99F	△	11.99												
-12.0 F	●	12.0												
-12.01F	△	12.01												
-12.02F	△	12.02												
-12.03F	△	12.03												
-12.04F	△	12.04												
-12.05F	△	12.05												

★PL means chamfering length to φDC.

★DCN is the front end bore diameter without bottom teeth, thus please make sure predrilled hole should be larger than φDCN.

★Turning skill reamer is recommended to use on NC Lathe. P.142

★OH Type is also available.

★Please slightly decrease feed rate before reaching the bottom of the hole without using G86.

HSS

FOR THROUGH HOLE

FOR STEPPED HOLE