



# CNC ROTARY TABLE with AR21 CONTROLLER



## CNC105AR21-04



Powerful Clamping Torque : 205Nm




Air purge function is provided.


## CNC180AR21-04



CNC180AR21-04 (400W) is standard. CNC180AR21-08 (750W) and CNC180AR21-06 (High Torque) are available.



Powerful Clamping Torque : 303Nm




Air purge function is provided.


## CNC202AR21-08



CNC202AR21-08 (750W) is standard. CNC202AR21-06 (High Torque) is available.




Powerful Clamping Torque : 303Nm




Air purge function is provided.


## CNC205AR21-05



CNC205AR21-05 (450W) is standard. ★Built-in type rotary joint 6+1 can be mounted.



Powerful Clamping Torque : 380Nm





Air purge function is provided.

Rotary joint shown in photo is optional.

## NCT200AR21-08



Powerful Clamping Torque : 900Nm





Air purge function is provided.

## CNC260AR21-08, 302AR21-08

CNC260, 302AR21-08 (750W) is standard. CNC260, 302AR21-06 (High Torque) is available.



CNC260



M-SIGNAL